

Service Bulletin No. 0004

Subject

Veronte OPS, release 6.12.28.

Compliance Consideration

Embention considers this Service Bulletin as **mandatory**.

Models affected

All Veronte Autopilots running any firmware release in 6.12 and any release of Veronte OPS prior to revision 6.12.28.

Effectivity date

01/03/2024

Compliance time

This Service Bulletin is **mandatory before the next flight**.

Purpose

The purpose of this bulletin is to inform about the software update of Veronte OPS to release 6.12.28. This is needed to prevent undesired behavior to the Veronte Autopilot.

VOPS Release Notes: 6.12.26 → 6.12.28

Added:

- Active AP is indicated with an icon.
- You can select an specific AP inside the 4x group.

Removed:

- Operation Panel 'Enter' keyboard event. This event was allowing to send Position command at any flight phase that could lead to undesired behavior.

Instructions

Veronte OPS update instructions can be found at <https://manuals.embention.com/veronte-ops/en/latest/index.html>

Material required

- Veronte OPS Website or Desktop version.

Note

Go to <https://manuals.embention.com/joint-collaboration-framework/en/0.1/index.html> for help finding the latest software versions at the Joint Collaboration Framework.